

SQAS Summary Report

Safety and Quality Assessment for Sustainability


Clean-Wash by Pellegrini Trasporti S.r.l. Nogarole Rocca (VR)

Report:	87020	Module:	Tank Cleaning
Date:	December 19, 2018	Assessor:	Papini, S.
Country:	Italy	First assessment:	No

Overall score of the company: 86%

Industry Range of scores per section

This chart shows the average scores of every SQAS section of the company report and the averages scores attributed to companies belonging to the same SQAS module.



The SQAS summary report is a statement of facts and this does not express any appreciation of the company's performance. The SQAS assessment is valid for 3 years.